

Structure No: 3643 - PHOTO SHEETmainroads
WESTERN AUSTRALIARoad Name: Trevena Rd
Crossing: Preston RiverLGA: Donnybrook - Balingup
SLK: 0.69Inspection Date: 24-Jan-2018
Inspector: Jarrod Pink

Photo No. 1: Overall view from abutment 1. (Taken: 24-Jan-2018)



Photo No. 2: Left hand side view from abutment 1. (Taken: 24-Jan-2018)

Structure No: 3643 - PHOTO SHEET



Road Name: Trevena Rd
Crossing: Preston River

LGA: Donnybrook - Balingup
SLK: 0.69

Inspection Date: 24-Jan-2018
Inspector: Jarrod Pink



Photo No. 3: Right hand side view from abutment 1. (Taken: 24-Jan-2018)



Photo No. 4: Left hand side wingwall at abutment 1. (Taken: 24-Jan-2018)

Structure No: 3643 - PHOTO SHEET

Road Name: Trevena Rd
Crossing: Preston River

LGA: Donnybrook - Balingup
SLK: 0.69

Inspection Date: 24-Jan-2018
Inspector: Jarrod Pink



Photo No. 5: Abutment 1 face from left hand side. (Taken: 24-Jan-2018)



Photo No. 6: Right hand side wingwall at abutment 1. (Taken: 24-Jan-2018)

Structure No: 3643 - PHOTO SHEETmainroads
WESTERN AUSTRALIARoad Name: Trevena Rd
Crossing: Preston RiverLGA: Donnybrook - Balingup
SLK: 0.69Inspection Date: 24-Jan-2018
Inspector: Jarrod Pink

Photo No. 7: Left hand side wingwall at abutment 2. (Taken: 24-Jan-2018)



Photo No. 8: Abutment 2 face from left hand side. (Taken: 24-Jan-2018)

Structure No: 3643 - PHOTO SHEETmainroads
WESTERN AUSTRALIARoad Name: Trevena Rd
Crossing: Preston RiverLGA: Donnybrook - Balingup
SLK: 0.69Inspection Date: 24-Jan-2018
Inspector: Jarrod Pink

Photo No. 9: Right hand side wingwall at abutment 2. (Taken: 24-Jan-2018)



Photo No. 10: Stringer layout in span 3 from left hand side. (Taken: 24-Jan-2018)

Structure No: 3643 - PHOTO SHEET



mainroads
WESTERN AUSTRALIA

Road Name: Trevena Rd
Crossing: Preston River

LGA: Donnybrook - Balingup
SLK: 0.69

Inspection Date: 24-Jan-2018
Inspector: Jarrod Pink



Photo No. 11: Pier 2 layout from left hand side. (Taken: 24-Jan-2018)



Photo No. 12: Left hand side v-barrier at abutment 1 end. (Taken: 24-Jan-2018)

Structure No: 3643 - PHOTO SHEETmainroads
WESTERN AUSTRALIARoad Name: Trevena Rd
Crossing: Preston RiverLGA: Donnybrook - Balingup
SLK: 0.69Inspection Date: 24-Jan-2018
Inspector: Jarrod Pink

Photo No. 13: Right hand side v-barrier at abutment 1 end. (Taken: 24-Jan-2018)



Photo No. 14: Bitumen seal cracking along kerb line from abutment 1. (Taken: 24-Jan-2018)

Structure No: 3643 - PHOTO SHEETmainroads
WESTERN AUSTRALIARoad Name: Trevena Rd
Crossing: Preston RiverLGA: Donnybrook - Balingup
SLK: 0.69

Inspection Date: 24-Jan-2018

Inspector: Jarrod Pink



Photo No. 15: Right hand side v-barrier from abutment 1 wingwall. (Taken: 24-Jan-2018)



Photo No. 16: Abutment 2 right hand side barrier, broken. (Taken: 24-Jan-2018)

Structure No: 3643 - PHOTO SHEET

Road Name: Trevena Rd
Crossing: Preston River

LGA: Donnybrook - Balingup
SLK: 0.69

Inspection Date: 24-Jan-2018
Inspector: Jarrod Pink



Photo No. 17: Right hand side rail damaged at corner, abutment 1. (Taken: 24-Jan-2018)



Photo No. 18: Right hand side top rail, above pier 1 damaged. (Taken: 24-Jan-2018)

Structure No: 3643 - PHOTO SHEETmainroads
WESTERN AUSTRALIARoad Name: Trevena Rd
Crossing: Preston RiverLGA: Donnybrook - Balingup
SLK: 0.69Inspection Date: 24-Jan-2018
Inspector: Jarrod Pink

Photo No. 19: Right hand side bottom rail, abutment 2 end damaged. (Taken: 24-Jan-2018)



Photo No. 20: Termite nest in base of tree at abutment 2 right hand side, at barrier termination. (Taken: 24-Jan-2018)

Structure No: 3643 - PHOTO SHEET**mainroads**
WESTERN AUSTRALIARoad Name: Trevena Rd
Crossing: Preston RiverLGA: Donnybrook - Balingup
SLK: 0.69Inspection Date: 24-Jan-2018
Inspector: Jarrod Pink

Photo No. 21: Span 3, 6 unsound deck ends from pier 3 towards abutment 2. (Taken: 24-Jan-2018)

Structure No: 3643 - PHOTO SHEET

Road Name: Trevena Rd
Crossing: Preston River

LGA: Donnybrook - Balingup
SLK: 0.69

Inspection Date: 15-Mar-2018
Inspector: Paul Olsen



Audit Photo No. 1: Span 1 LHS, deck ends U/S. (Taken: 15-Mar-2018)



Audit Photo No. 2: Span 1 RHS, deck ends intermittently U/S. (Taken: 15-Mar-2018)

Structure No: 3643 - PHOTO SHEETmainroads
WESTERN AUSTRALIA

Road Name: Trevena Rd

LGA: Donnybrook - Balingup

Inspection Date: 15-Mar-2018

Crossing: Preston River

SLK: 0.69

Inspector: Paul Olsen



Audit Photo No. 3: Abutment 2 bedlog RHS, scour is beginning to compromise footing. (Taken: 15-Mar-2018)

File: 04/4520
To: Engineer Bridge Loading
Subject: Bridge Number: 3643

1. Having recently completed an assessment of routine and specific maintenance work required on this bridge, I am of the opinion that the condition of certain structural components has deteriorated to such an extent that the load carrying capacity of the bridge may have been affected.
2. In accordance with the requirements of the procedure for Heavy Loads Assessment, Document number 3912/01-7, this bridge is referred for a detailed structural assessment of the bridge in its present condition.



Paul Olsen
Engineering Associate
20 March 2018

Span 1 str 5
Bridge is scheduled for replacement
in late 2018



Enquiries: Gavin Johnston on 9323 4431
 Our Ref: 04/4520
 Your Ref:



ABN: 50 860 676 021

**ASSET MANAGER STRUCTURES
 SOUTH WEST REGION**

Structure No.: 3643
 Over: Preston River
 On: Trevena Rd (2170045)
 SLK: 0.69
 LGA: Shire of Donnybrook - Balingup

1. Please find enclosed a copy of the Detailed Inspection Report for the above Local Authority structure.
2. Attached is a schedule of maintenance items that are required to be undertaken in order to maintain structural integrity and extend the life of the Structure.
3. The maintenance items have been entered into IRIS for programming purposes.
4. Preliminary examination has indicated that the load carrying capacity of this Structure may have been affected by the deterioration of structural components as listed in the attached report. We are in the process of determining its current load capacity and will advise you accordingly when our assessment is completed.
5. This report details all components inspected. Some components have not been inspected due to inaccessibility.


 Gavin Johnston
 BRIDGE CONDITION MANAGER

5/7/18

Enc

WORK ITEMS - TIMBER BRIDGES
BRIDGE No: 3643

ITEM NO	ITEM DESCRIPTION	WORK REQD	PRIORITY CODE	COMMENTS
---------	------------------	-----------	---------------	----------

(A) GENERAL MAINTENANCE

G005	Bridge - Durability Survey (L3)			
G009	Bridge - Load Rating	Y	0	Span 1 Stringers
G010	Bridge - Monitor Defect	Y	1	Abut 2 Bedlog - Scour

(B) PREVENTATIVE MAINTENANCE

P101	Bridge - Seal Timber	Y	1	
P102	Bridge - Maintain Fastener			
P103	Bridge - Fungicide Treatment	Y	1	

(C) ROUTINE MAINTENANCE

	Bearing - Maintain			
	Bridge - Remove Graffiti			
	Bridge - Repair Scour (Minor)			
	Bridge - Eradicate Termites	Y	1	
	Bridge - Clear Debris and Vegetation	Y	1	vegetation
	Deck Joint - Maintain			
	Deck Surface - Maintain	Y	1	spans 1 to 3 LHS & RHS
	Drainage - Maintain			
	Expansion Joint - Maintain			
	Fence - Remove			
	Fence - Repair (Control of Access)			
	Guardrail Maintain/Repair	Y	0	spans 1 to 3 LHS & RHS
	Kerb - Repair (Minor) - Non Structural			
	Lighting - Maintain			
	Sign - Maintain	Y	1	widthmarker at RHS

(D) SPECIFIC MAINTENANCE

S315	Bridge - Replace Fastener <1.5m			
S350	Bridge - Repair Scour (Major)	Y	2	abutment 2
S366	Bridge - Access - Improve	Y	2	spans 1 & 3
S413	Deck - Repair			
S437	Decking - Repair (Timber)	Y	2	spans 1 & 2 LHS, spans 1 to 3 RHS
S449	Drainage - Repair			
S455	Expansion Joint - Repair			
S461	Footpath - Repair			
S501	Abutment - Reconstruct			
S504	Abutment - Repair (Non timber)			
S507	Bedlog - Repair	Y	2	wingwalls at 1 & 2 LHS & RHS
S510	Bedlog - Shim			
S522	Corbel - Bolt			
S525	Corbel - Repair			
S528	Corbel - Shim			
S537	Footpath Railing - Repair			
S540	Fullcap - Repair			
S543	Halfcap - Improve Bearing			
S546	Halfcap - Pack			
S549	Halfcap - Repair			
S558	Pier - Repair			
S561	Pile - Band			
S564	Pile - Repair			
S570	Sheeting - Repair			
S582	Waler - Replace			
S607	Bearer - Repair			
S643	Joist - Repair			
S655	Stringer - Bolting	Y	2	span 2 str 2 & 5
S661	Stringer - Repair			
S667	Stringer - Shim			

PRIORITY CODE

- 0 - Critical Safety Deficiency : EMERGENCY action required (Immediate or within 6 months)
 1 - Very High Priority (Within 3 years)
 2 - Medium Priority (Within 4 years)
 3 - Low Priority (Within 5 years-assess again at next Detailed Inspection)

MRWA Ref: 04/4520

DETAILED TIMBER BRIDGE INSPECTION SUMMARY

Bridge No:	3643	Region:	SOUTH WEST REGION
River Name:	Preston River	SLK:	0.69
Road:	Trevena Rd	Road No:	2170045
LGA:	Shire of Donnybrook - Balingup		

1.0 General

Bridge no. 3643 located on Trevena Rd in the Shire of Donnybrook - Balingup is a three span bridge crossing the Preston River. The structure requires significant maintenance in particular the timber decking is beginning to fail in multiple locations and scour is beginning to compromise the abutment 2 bedlog. The structure has been recommended for load rating due to an element that has returned poor drilling results.

2.0 Preventative Maintenance

Preventative maintenance to be undertaken on a 5 year periodic basis. Areas of concern have been identified below. Sealing of timber elements in accordance with Specification 850 is required. Fungicide treatment of all timber elements in accordance with Specification 850 is required.

3.0 Routine Maintenance

Undertake termite inspection and treatment as required in accordance with specification 850.93.09.
Vegetation and Debris clearing shall be undertaken as outlined in report in accordance with specification 850.93.08.
Correct road surface on bridge deck and approaches as outlined in report.
Undertake guardrail maintenance as outlined in report.
Replace signs and lights as outlined in report.

4.0 Specific Maintenance**4.1 Substructure**

Undertake scour repairs as outlined in report.
(abutment 2)
Undertake works to improve access for elements not inspected.
(spans 1 & 3)

4.2 Superstructure


Undertake timber decking repairs as outlined in report.
(spans 1 & 2 LHS, spans 1 to 3 RHS)
Undertake bedlog repairs as outlined in report.
(wingwalls a1 & a2 LHS & RHS)
Bolt and or seal stringers as outlined in report in accordance with specification 850.29/850.30
(span 2 str 2 & 5)

5.0 BCI

68.4

6.0 Load Rating

Span 1, str 5



Paul Olsen
Engineering Associate Bridges

March 20 2018

**DETAILED VISUAL (LEVEL 2) TIMBER
BRIDGE INSPECTION REPORT
BRIDGE CONDITION INDEX (BCI)**



Bridge Number **3643**

In conjunction with the Detailed Level 2 Bridge Inspection Report (as dated below), a Bridge Condition Index (BCI) has been calculated for this Bridge. The BCI assigns a numerical value to a bridge that is indicative of its condition and provides a relative condition in comparison with other timber bridges (BCI calculation is only applicable for timber bridges). The BCI rating system is a tool to provide a systematic approach for the determination of bridge condition by bridge inspection alone.

The process for determining the BCI is outlined in the Timber Bridge Condition Index User Guide. The BCI is primarily calculated utilising Condition States which are assigned based on the Level 2 Bridge Inspection Report (see attached).

A summary of the condition states and the calculated BCI for this bridge is provided below.

Condition States from Detailed Inspection Report conducted on 24-01-2018

LOCATION	Weighting	Condition State - Distribution (%)				Ave AGR	BCI
		CS1	CS2	CS3	CS4		
Condition State Weighting		1	3	9	11		
Stringers	11	17.4	18.3	3.0	61.3	68.4	
Pier Piles	11	65.5	34.5	0.0	0.0		
Abutment Piles	11	0.0	0.0	0.0	0.0		
Halfcaps	11	0.0	100.0	0.0	0.0		
Corbels	6	0.0	100.0	0.0	0.0		
Timber Decking	6	0.0	80.0	0.0	20.0		
Wing Piles	3	6.2	0.0	0.0	93.8		
Abutment Sheeting	3	0.0	100.0	0.0	0.0		
						45.6	
						22.8	
						20.1	

Descriptor	BCI Range
Very Good	
Good	20 - 39
Fair	40 - 55
Poor	56 - 100
Severe	

BCI Descriptor Range (Refer Table 5.1 Doc No. 6706/02/2232)

Comments:

Numerous elements have not been inspected due to low headroom

Prepared by: P Olsen

Date: 28/02/2018



**TIMBER BRIDGE
DETAILED INSPECTION REPORT**



GENERAL INFORMATION - SHEET 1


Bridge No.: 3643

Region:	<u>South West</u>	Latitude (S):	<u>-33.54048</u>
		Longitude (E):	<u>115.92275</u>
Road Name:	<u>Trevena Rd</u>	Road No.:	<u>2170045</u>
Local Government:	<u>Donnybrook - Balingup</u>	Owner:	<u>Local Authority</u>
Crossing Name:	<u>Preston River</u>	SLK:	<u>0.69</u>
Number of Lanes:	<u>1</u>	Length (m):	<u>18.45</u>
Total Width (m):	<u>4.45</u>	Max. Head Room (m):	<u>3.40</u>
<small>Incl Footpath</small>		Min. Head Room (m):	<u> </u>
No. of Spans:	<u>3</u>	Width between Kerbs (m):	<u>4.15</u>
		Concrete Overlay (Y/N):	<u>N</u>

Piers are numbered along the bridge in ascending order from ABUTMENT 1 to ABUTMENT 2.
Piles are numbered across the bridge in ascending order from LEFT to RIGHT.
Stringers are numbered across the bridge in ascending order from LEFT to RIGHT.

Inside and outside kerb depths noted in corners of sketch.

Exposed Deck Ends (RCO only): LHS RHS



This bridge has been inspected in accordance with the requirements of the Main Roads Western Australia Timber Bridge Detailed Inspection Guidelines.

Inspected by: LW Sp
Date: 24/1/18
Drilled by: Sp

Checked by: COLIN P. MURKIN
Date: 15-3-18



SITE CONDITIONS
Bridge No: 3643



DRIVE THROUGH	Visible Line of Sight from Abut. 1: <i>60 mtrs</i> Visible Line of Sight from Abut. 2: <i>90 mtrs</i>
TRAFFIC CONTROL <i>(Describe if different to the generic T&P)</i>	Abut. 1 end: } Abut. 2 end: } <i>1 mtr on shoulder</i>
PARKING POSITION	> 3 m <input type="checkbox"/> Position: 1.2 to 3 m <input type="checkbox"/> Position: 0 to 1.2 m <input checked="" type="checkbox"/> Position: <i>A1 LHS</i>
ACCESS TO ABUTMENTS <i>(Describe access conditions at each wing)</i>	Abutment 1: LHS } RHS } <i>down steep banks</i> Abutment 2: LHS } RHS } <i>as above</i> Vegetation: <i>Long grass</i>
ACCESS TO PIERS <i>(Describe access conditions along each side of the structure)</i>	LHS: } RHS: } <i>in water</i> Vegetation: <i>OK</i>
POTENTIAL HAZARDS	Railing/Posts: Bolts: Services: Asbestos: Other: <i>steep banks low hanging flashing</i>
FENCES	Timber <input type="checkbox"/> Location: <i>none</i> Wire/Mesh: <input type="checkbox"/> Location: Electrified: <input type="checkbox"/> Location: Barbed Wire: <input type="checkbox"/> Location: Other (Specify): <input type="text"/> Location:
WATER	Depth (m): <i>3</i> Flow Rate: <i>slow</i> Algae: <i>no</i> (Access may be restricted by toxic algae) Tide: <i>no</i> Location: <i>span 2</i>
POWERLINES	Side of bridge: <i>none</i> Horizontal distance from edge of deck (m): Estimated vertical height above deck (m):

Signature: 

Date: 24/1/18



**TIMBER BRIDGE
DETAILED INSPECTION REPORT**



GUARDRAIL INFORMATION

Bridge No.: **3643**

Barrier Type

- None
- RHS Rails No. of Rails (on bridge)
- Thriebeam
- W Beam
- Tric-Bloc Concrete Barrier
- Reinforced Concrete Barrier (Type F)
- Constant Slope Concrete Barrier
- Other Concrete Profiles

Approach 1			On Bridge			Approach 2		
LHS	Median	RHS	LHS	Median	RHS	LHS	Median	RHS

Post Type

- None
- Concrete
- Timber
- Steel Type: _____

Approach 1			On Bridge			Approach 2		
LHS	Median	RHS	LHS	Median	RHS	LHS	Median	RHS
X		X	X		X	X		X

[Types: C-Section (C), I Section (I), RHS (R), Square Hollow Section SHS (S), Tubular (T), Steel PFC (PFC), Steel Channel (Ch)]

Off bridge

- Number of Posts off Bridge
- Length of Barrier off Bridge (m)

3		3		3		3
4.6		4.6		4.6		4.7

Visibility Barrier

- Timber No. of Rails (on bridge)
- Steel Pipe(s) No. of Pipes (on bridge)
- Guide Posts
- Balustrade

Approach 1			On Bridge			Approach 2		
LHS	Median	RHS	LHS	Median	RHS	LHS	Median	RHS
X		X	X		X	X		X

Top Rails

- Steel Pipe
- Steel RHS/Channel
- Steel C Section
- Timber

X		X	X		X	X		X

End Terminals

Approved End Terminal Types

- WAMELT
- SKT-350
- ET-2000
- X Tension
- TAU II Crash Cushion
- Other

Approach 1			On Bridge			Approach 2		
LHS	Median	RHS	LHS	Median	RHS	LHS	Median	RHS

Other End Terminal Types

- None
- Turn-down
- Bullnose
- Fishtail
- Other

X		X				X		X

Structural problem found? (Y/N)

Y
L + RHS V/Barrier is leaning forwards

If yes, comment below.

See photo + A2 RHS barrier is broken: See photo



**TIMBER BRIDGE
DETAILED INSPECTION REPORT**



ROUTINE INFORMATION

Bridge No.: 3643

SCUFPERS LOCATION, TYPE & CONDITION <small>(R204)</small>	None <input type="checkbox"/> LIIS <input checked="" type="checkbox"/> RIIS <input checked="" type="checkbox"/>	Box <input type="checkbox"/> PVC pipe <input type="checkbox"/> Hole in deck <input type="checkbox"/>
		Through Deck <input type="checkbox"/> Through Kerb <input checked="" type="checkbox"/>
<i>note old hole thru timber kerb not in use due to Road been Sealed</i>		
FLASHING TYPE & CONDITION <small>(R204)</small>	None <input checked="" type="checkbox"/>	PVC pipe <input type="checkbox"/> PGI <input type="checkbox"/>
BOLT TIGHTENING REQUIRED <small>(P102)</small>	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>
TERMITES <small>(R204)</small>	Active <input checked="" type="checkbox"/>	Not Active <input type="checkbox"/>
PREVENTATIVE FUNGICIDE <small>(P103)</small>	Treated <input checked="" type="checkbox"/>	Not Treated <input type="checkbox"/>
ATTACHED FENCES & OTHER WATERWAY OBSTRUCTIONS <small>(R210)</small>	<i>old trees piece 1 R/S RIIS CLEARING</i>	
ROAD SURFACE & KERBING CONDITION <small>(R207)</small>	ON BRIDGE	Road Surface: <i>Bitumen seal Cracking along both sides A1 to A2 See photo</i>
		Kerbing: <i>Timber : Buried</i>
	APPROACHES	Road Surface: <i>asphalt : minor wear</i>
		Kerbing: <i>none</i>
VEGETATION <small>(R205)</small>	Requires Clearing : LIIS <input checked="" type="checkbox"/>	Abut 1 <input checked="" type="checkbox"/> RIIS <input checked="" type="checkbox"/> Abut 2 <input checked="" type="checkbox"/>
<i>Large trees & small trees Long grass.</i>		
STREAM BED CONDITION <small>(R203)</small>	<i>Rocky / sandy</i>	
SERVICES <small>(Type, Size & Location)</small>	Type	Size (mm)
	<i>Telstra</i>	<i>50</i>
BRIDGE CONDITION	Low <input type="checkbox"/>	Priority for Engineering Assessment Medium <input checked="" type="checkbox"/> High <input type="checkbox"/> Urgent <input type="checkbox"/>

Comments: *Timber Kerb has started to lean outwards Resulting in both sides of the V/barrier leaning outwards
Repair Required*



**TIMBER BRIDGE
DETAILED INSPECTION REPORT**



GENERAL INFORMATION - SHEET 2

Bridge No.: 3643

Bridge Status Built/In Use Not Used
 Date Built 16/06/1964 Skew (angle) _____ Skewed Width (m) _____

Widening Left Hand side Width (m) _____ Right Hand side Width (m) _____
 Date _____ Date _____

Surface Type Unsurfaced Bitumen Seal Asphalt
 Rubberised Seal Tiles Steel Plate

Pavement Type Unpaved Gravel Material Unknown

Footpath Left Left Kerb (m) 0.15 Path (m) _____ Right Kerb (m) _____
 Footpath Right Left Kerb (m) _____ Path (m) _____ Right Kerb (m) 0.15
 Median Left Kerb (m) _____ Median (m) _____ Right Kerb (m) _____

Bridge Function 1 Road Bridge Rail Bridge Pedestrian Bridge

Bridge Function 2 Over Water Over Road Over Rail
 Over Road & Rail Over Road & Water Over Rail & Water
 Stock Underpass Pedestrian Underpass

SIGNAGE

Load Limits Abutment 1 End Tonne Abutment 2 End Tonne

Width Markers Abutment 1 LHS RHS Abutment 2 LHS RHS

Is position of Width Markers a true indication of the bridge width? (Y/N) *Y - S.M.C. 1/2012 (1)*
X - INSTALL

Other Signs	Abutment 1	LHS	<input type="checkbox"/>	RHS	<input type="checkbox"/>	Abutment 2	LHS	<input type="checkbox"/>	RHS	<input type="checkbox"/>
No Overtaking or Passing	Abutment 1	LHS	<input type="checkbox"/>	RHS	<input type="checkbox"/>	Abutment 2	LHS	<input type="checkbox"/>	RHS	<input type="checkbox"/>
No Overtaking on Bridge	Abutment 1	LHS	<input type="checkbox"/>	RHS	<input type="checkbox"/>	Abutment 2	LHS	<input type="checkbox"/>	RHS	<input type="checkbox"/>
One Lane Bridge	Abutment 1	LHS	<input type="checkbox"/>	RHS	<input type="checkbox"/>	Abutment 2	LHS	<input type="checkbox"/>	RHS	<input type="checkbox"/>
Low Clearancem	Abutment 1	LHS	<input type="checkbox"/>	RHS	<input type="checkbox"/>	Abutment 2	LHS	<input type="checkbox"/>	RHS	<input type="checkbox"/>
Narrow Bridge Sign	Abutment 1	LHS	<input checked="" type="checkbox"/>	RHS	<input type="checkbox"/>	Abutment 2	LHS	<input type="checkbox"/>	RHS	<input checked="" type="checkbox"/>
Give Way	Abutment 1	LHS	<input type="checkbox"/>	RHS	<input type="checkbox"/>	Abutment 2	LHS	<input type="checkbox"/>	RHS	<input type="checkbox"/>

Crossing Sign: _____

Other Abutment 1 LHS RHS Abutment 2 LHS RHS
 Abutment 1 LHS RHS Abutment 2 LHS RHS

Signage Condition Legend Good 1 Poor 3 Not Required
 Fair 2 None (missing) 4

note A1 LHS has a Small Type W/marker



TIMBER BRIDGE
DETAILED INSPECTION REPORT



ELEMENT SPACING SHEET 2


Bridge No.: 3643

All measurements (cumulative) are taken from the reference point as indicated by the star ☆


Pier Pile Centres

Mark in RHS edge of deck and dimension last pile to RHS edge of deck


PIER No. *1. typical*



PIER No.



PIER No.




Typical Stringer Spacing


Mark in RHS edge of deck and dimension last stringer to RHS edge of deck

Note: Stringer spacings must be measured in every span with additional stringers. Use additional sheets as required


SPAN No. *1. typical*



SPAN No.



SPAN No.







**TIMBER BRIDGE
DETAILED INSPECTION REPORT**



BEDLOG ABUTMENTS

Abutment No. 1

Bridge No: 3643



* = Drill Location

Bedlog	Vert (mm)	Mat Type	Drilling (mm)	BELOW STRINGER NUMBER											Condition State	Bolt reqd		
				1	2	3	4	5	6	7	8	9	10	11				
1	340	JAR	Solid (Front)	*	*	*	*	*										
			Rot Pipe															
			Solid (Rear)															

Bedlog No	LHS					CENTRE LINE				RHS			
	Face	Solid	Rot	Pipe	Bolt reqd	Solid	Rot	Pipe	Bolt reqd.	Solid	Rot	Pipe	Bolt reqd
3	Front												
	Rear												
4	Front												
	Rear												
5	Front												
	Rear												
6	Front												
	Rear												
7	Front												
	Rear												
8	Front												
	Rear												

Bedlog - Wing Walls: LHS: Bed log 1 is o/s Repair Saturated Bedlogs: _____
 RHS: Bed Log 1 is o/s Bed log 2 is so to back _____
 Sheeting: LHS: _____
 CENTRE LINE: _____
 RHS: _____

Comments: * Unable to drill due to low H/room.
Heavy Scouring A1 end



TIMBER BRIDGE
DETAILED INSPECTION REPORT



PIER No: 1

Bridge No: 3643

Pile No	Circ (mm)	Dia (mm)	Timber Drilling (mm)			Extent of Rot (m)			Splice		Blaze Markings			Halfcaps Bearing (mm)		Pile Circ (mm) below HC (5m*)	Mat Type	Cond State
			Solid	Rot	Pipe	Drill Location from top HC	Below	Above	Location	Requires Band	Marking (H-m)	Height Top HC to Blaze (m)	Height Blaze to GL (m)	A1	A2			
1	1300	410	285									20	.7	1.6	160	160	JAR	2
2	1410	450	225									20	.7	1.6	160	150	JAR	2
3	1300	410	285									20	.7	1.6	160	160	JAR	2
4																		
5																		
6																		
7																		
8																		
9																		
10																		

Total Number of Corbels: 5 Typical Corbel Height (mm): LHS 380 RHS 380

Corbel No:

Material Type:

Requires Bolting:

Condition State:

1	2	3	4	5	6	7	8	9	10	11	12	13	14
JAR	JAR	JAR	JAR	JAR									
all bolted													
A1/A2 End													
A1/A2 End													

Ironwork Condition: minor rust

Tightening Required: No

Walers Size V x H

Bracing Size V x H

Saturated Piles:

LHS Halfcaps Size V 350 H 160 Length 4600 No. of 2 Gap between H/Caps 160


Top of H/Caps to underside of Deck 730 H/Cap Material J

RHS Halfcaps Size V H Length No. of Gap between H/Caps

Top of H/Caps to underside of Deck H/Cap Material

Are there more than 2 sets of halfcaps or sill beams (YES/NO) NO (If yes record details on comments sheet)

Comments: Both H/Caps have numerous G/Veins T/lost





**TIMBER BRIDGE
DETAILED INSPECTION REPORT**



PIER No: 2

Bridge No: 3643

Pile No	Circ (mm)	Dia (mm)	Timber Drilling (mm)			Extent of Rot (m)			Splits		Blaze Markings			Halfcaps Bearing (mm)		Pile Circ (mm) below HC (5m*)	Mat Type	Cond State
			Solid	Rot	Type	Drill Location from top HC	Below	Above	Location	Requires Band	Marking (ft m)	Height Top HC to Blaze (m)	Height Blaze to GL (m)	A1	A2			
1	1100	350	175									21	.7	1.8	100	130	JAR	2-
2	1210	390	195									21	.7	1.8	140	120	JAR	2-
3	1100	350	175									21	.7	1.8	120	160	JAR	2-
4																		
5																		
6																		
7																		
8																		
9																		
10																		

Total Number of Corbels: 5 Typical Corbel Height (mm): LHS 380 RHS 360

Corbel No	1	2	3	4	5	6	7	8	9	10	11	12	13	14
Material Type	JAR	JAR	JAR	JAR	JAR									
Requires Bolting	A1/A2 End	A1/A2 End	A1/A2 End	A1/A2 End	A1/A2 End									
Condition State:	A1/A2 End	A1/A2 End	A1/A2 End	A1/A2 End	A1/A2 End									

Ironwork Condition: minor rust Tightening Required No

Walers Size V x H

Bracing Size V x H


Saturated Piles:

LHS Halfcaps Size V 350 H 160 Length 4600 No. of 2 Gap between H/Caps 160
 Top of H/Caps to underside of Deck 730 H/Cap Material J
 RHS Halfcaps Size V H Length No. of Gap between H/Caps
 Top of H/Caps to underside of Deck H/Cap Material

Are there more than 2 sets of halfcaps or sill beams (YES/NO) No (If yes record details on comments sheet)

Comments both H/Caps have numerous G/veins / look

in 100's etc 25 2000






TIMBER BRIDGE
DETAILED INSPECTION REPORT



BEDLOG ABUTMENTS

Abutment No. 2

Bridge No: 3643



● = Drill Location

Bedlog	Vert (mm)	Mat Type	Drilling (mm)	BELOW STRINGER NUMBER												Condition State		
				1	2	3	4	5	6	7	8	9	10	11	12			
1	300	JAR	Solid (Front)	*	*	*	*	110										2
			Rot Pipe				To Back											
			Solid (Rear)				0											

Bedlog No	LHS					CENTRE LINE				RHS			
	Face	Solid	Rot	Pipe	Bolt reqd.	Solid	Rot	Pipe	Bolt reqd.	Solid	Rot	Pipe	Bolt reqd.
3	Front												
	Rear												
4	Front												
	Rear												
5	Front												
	Rear												
6	Front												
	Rear												
7	Front												
	Rear												
8	Front												
	Rear												

Bedlog - Wing Walls: LHS Bedlog 1 is up Bedlog 2 is 60 To back? Saturated Bedlogs: _____
 RHS Bedlog 1 is up

Sheeting: LHS _____
 CENTRE LINE _____
 RHS _____

Comments: both W/Wall Bedlogs are in poor Condition
 Heavy Scouring of face
 POSSIBLE MOVEMENT IN ABUTMENT 2 BEDLOG SUPPORTS IS
 POOR RHS - SEE SUBJECT PHOTOS



TIMBER BRIDGE
DETAILED INSPECTION REPORT



DETAIL SHEET

Span No: 1

Bridge No: 3643

Stringer No:	1	2	3	4	5	6	7	8	9	10	11	12	13	14	
Material Type:	JAR	JAR	JAR	JAR	JAR										
H Diameter (mm)	400	420	400	470	380										
V Measurement (mm)	350	350	350	350	350										
Abutment 1 End	Drill Vertical	Solid (B)	*	*	*	*	*								
		Rot	120				150								
		Pipe													
		Rot													
		Solid (T)													
	Drill Horiz	Left	80				90								
		Right	200				110								
	Split	V Bolt Rqd													
		H Bolt Rqd													
	Propped														
Condition State	3	-	-	-	4										

H Diameter (mm)	400	440	400	470	380										
V Measurement (mm)	500	420	450	430	500										
Mid Span	Drill Vertical	Solid (B)	480	180	450	480	480								
		Rot													
		Pipe		80											
		Rot													
		Solid (T)		160											
	Drill Horiz	Left													
		Right													
	Split	V Bolt Rqd													
		H Bolt Rqd													
	Propped														
Condition State	1	2	1	1	1										

all Results Given at 480 mm bit size

H Diameter (mm)	350	480	400	470	380										
V Measurement (mm)	350	350	350	350	350										
Abutment 2 End	Drill Vertical	Solid (B)	180	170	130	140	110								
		Rot													
		Pipe	60	80	120	60	100								
		Rot													
		Solid (T)	110	100	100	150	140								
	Drill Horiz	Left													
		Right													
	Split	V Bolt Rqd													
		H Bolt Rqd													
	Propped														
Condition State	2	2	2	2	2										

Cond. of Spiking Plank Not Applicable Size V Condition S R %

Cond. of Decking (Solid/Rot) S 90 R 10 % Cond. of Deck Ends S 80 R 20 %

Decking Size (mm) V 100 x H 226 Decking Timber Type JAR

Span Length from Centreline Supports (m) 5.71 Clear Span Length 4.82 Saturated stringers: 5

Deck Condition State Condition 1 Condition 2 Condition 3 Condition 4 Percentage:

Spiral Grain Stringers: 4

Comments: str 1 At drilled tab from the face * Unable to drill due to low H/room

Deck ends w/s in left - str 1 not present

Deck ends w/s intermittent str 5 - see abutment 2

REPAIR 4 STRS



TIMBER BRIDGE
DETAILED INSPECTION REPORT



DETAIL SHEET

Span No: 2

Bridge No: 3643

Stringer No:	1	2	3	4	5	6	7	8	9	10	11	12	13	14
Material Type:	JAR	JAR	JAR	JAR	JAR									

H Diameter (mm)		420	410	400	490	390								
V Measurement (mm)		350	350	350	350	350								
Abutment 1 End	Drill Vertical	Solid (B)	350	170	350	350	120							
		Rot					90							
		Pipe		60										
		Rot												
		Solid (T)		120			140							
Drill Horiz	Left													
	Right													
Split	V Bolt Rqd													
	H Bolt Rqd													
Propped														
Condition State		1	2	1	1	2								

H Diameter (mm)		420	410	450	480	450							
V Measurement (mm)		500	450	430	500	460							
Mid Span	Drill Vertical	Solid (B)	220	220	430	480	100						
		Rot											
		Pipe	60	30			160						
		Rot											
		Solid (T)	200	200			200						
Drill Horiz	Left					160							
	Right					170							
Split	V Bolt Rqd												
	H Bolt Rqd		✓	✓		✓	✓						
Propped													
Condition State		2	2	1	1	2							

H Diameter (mm)		480	480	400	550	470							
V Measurement (mm)		350	350	350	350	350							
Abutment 2 End	Drill Vertical	Solid (B)	350	200	350	350	140						
		Rot		60									
		Pipe					70/60						
		Rot											
		Solid (T)		90			0						
Drill Horiz	Left					110							
	Right					180							
Split	V Bolt Rqd												
	H Bolt Rqd												
Propped													
Condition State		1	2	1	1	2							

Cond. of Spiking Plank Not Applicable Size V Condition S R %

Cond. of Decking (Solid/Rot) S 90 R 10 % Cond. of Deck Ends S 70 R 30 %

Decking Size (mm) V 100 x H 220 Decking Timber Type JAR

Span Length from Centreline Supports (m) 6.13 Clear Span Length 4.67 Saturated stringers: _____

Deck Condition State Condition 1 Condition 2 Condition 3 Condition 4 Percentage: Spiral Grain Stringers: _____

Comments:

DECK ENDS INDETERMINATELY V'S PARALLELS - REPAIR



TIMBER BRIDGE
DETAILED INSPECTION REPORT



DETAIL SHEET

Span No: 3

Bridge No: 3643

Stringer No:	1	2	3	4	5	6	7	8	9	10	11	12	13	14	
Material Type:	JAR	JAR	JAR	JAR	JAR										
H Diameter (mm)	540	470	530	530	460										
V Measurement (mm)	350	350	350	350	350										
Abutment 1 End	Drill Vertical	Solid (B)	140	160	350	350	160								
		Rot													
		Pipe	100	50			760p								
		Rot													
		Solid (T)	110	140			0								
	Drill Horiz	Left					130								
		Right					120								
	Split	V Bolt Rqd		✓											
		H Bolt Rqd		✓											
	Propped														
Condition State	2	2	1	1	2										

H Diameter (mm)	430	420	490	490	440										
V Measurement (mm)	480	440	470	500	480										
Mid Span	Drill Vertical	Solid (B)	480	160	470	480	270								
		Rot					50								
		Pipe		70											
		Rot													
		Solid (T)		110			160								
	Drill Horiz	Left													
		Right													
	Split	V Bolt Rqd		✓											
		H Bolt Rqd		✓											
	Propped														
Condition State	1	2	1	1	2										

H Diameter (mm)	400	400	470	480	420										
V Measurement (mm)	350	350	350	350	350										
Abutment 2 End	Drill Vertical	Solid (B)	*	*	*	*	*								
		Rot	130												
		Pipe													
		Rot													
		Solid (T)													
	Drill Horiz	Left	150				420 F								
		Right	120												
	Split	V Bolt Rqd													
		H Bolt Rqd													
	Propped														
Condition State	2	-	-	-	2										

Cond. of Spiking Plank Not Applicable Size V Condition S R %

Cond. of Decking (Solid/Rot) S 90 R 10 % Cond. of Deck Ends S 70 R 30 %

Decking Size (mm) V 100 x H 220 Decking Timber Type JAR

Span Length from Centreline Supports (m) 5.75 Clear Span Length 4.80 Saturated stringers: _____

Deck Condition State Condition 1 Condition 2 Condition 3 Condition 4 Percentage: 9.7 1.7 Spiral Grain Stringers: _____

Comments: note deck bog-weights from pier 3 are u/s 6 in total
 * Unable to drill due to low H/room
 DECK COND INSPECTIONALLY U/S AHS
 BIDS NOT REC